





Building Support Beams for Tower Beam

Peg Holding to Vert Build Beam

Rotten Tower Beam

Sawn newer building beam

Peg

Steel Bolt



A close-up photograph of a wooden beam joint. The main beam is heavily weathered and shows significant rot, with a large, irregular hole in the center. A newer, lighter-colored wooden beam is sistered to the bottom of the main beam. The background is dark and indistinct.

Rotten Beam

Newer sawn beam sistered to rotten



Rotted tower beam

newer building beam

Notice substantial support at bottom of rotted beam

Walls wet





Wet Walls & Floor





Building Support Beams for Tower Beam

Peg Holding to Vert Build Beam

Rotten Tower Beam

counter weight for clock

Not attached to wall on left

Support Building Beam
For Tower Beam

2 x 4 cross linked to another beam on left

Brace?

3 x 8? holding up
Beam

WITH CARE
HANDLE





Summit


2 x4 Bracing support beam tholding beam to tower

WITH CARE

TOW
CARE
HANDLE

Broken rotten peg between building beam on left rotten tower beam on right






rotten beam tower

wood peg

new post building


Walls wet framing on tower





Rotted Tower Beam

Superb Railing



Rotted Tower Beam

Superb Railing